Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Providing and laying HDPE water line in V R Layout in JP Park Ward No 17
2	Technical Sanction Estimate No. & Date	CE/RRNZ/TS/299/13-14 Dtd:18/09/2013 by CE (RRN)
3	Administration Approval & Date	JC/RRN/AS/2252/13-14 Dtd 17-09-2013 by JC (RRN)
4	Estimate Amount	Rs.49.96 Lakhs
5	Job Code No.	017-14-000020
6	P-Code	P2201
7	Agreement No & date	EE/RRND/AG No./227/2013-14 Dtd.06-02-2014
8	Work order Number & Date	EE/RRND/W.O/227/2013-14 Dtd.06-02-2014
9	Contract Amount as per Agreement	Rs.53,45,264/-
10	Bill Amount	Rs.40,66,393/-
11	B.R. No. & Date	250/2014-15 dt. 30-06-2014
12	Agency	M/s Damodar & Co
13	M.B. Number & Page No. of Measurement recordes	119/2013-14 Pages 11886 to 11892/2 [Xerox Copy of MB]
14	Date of Inspection	22/5/2016
15	Enclusures	1) Sketch Showing the Location of Site 2) 8 Number of photos taken during inspection of above site.
16	Inspection Report	The above site has been Inspected by me along with the concerned person. It is observed that the Items indicated in the MB are not suscepible for measurements. As such the photoes taken during the execution of work have been Scrutinised and Inspected - It is to the Xerox Copy of MB No 119/2013-14

The above work has been done. This has a reference

EE (RRND) RR Nagara

(R.Sathyanarayana) 22/5/2016
Inspection Report officer,

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು-560 054

Scanned by CamScanner